



Sideline Seats
 Hedge Wall Barrier
 Sideline Seat Lounge
 Field Level Service Area

Improved Bowl Tunnel (typ)
 Endzone seats to remain
 Seats removed
 Restricted Access
 Public Access
 New seat infill
 Existing seats removed below cc row

Improved Bowl Tunnel (typ)
 New seat infill
 Improved Field Access Tunnel
 Sideline Seats
 Upper row of hcp seating to remain
 Historic Field Wall
 New Field Wall
 Sideline Seat Lounge